

Sample Number	Site	Drop/Pick	Date Collected	Day	Hold	Date Subm	Lead	Lead p/b	Copper	Copper p/b	Address	City	Zip Code	FSID	SL Public	SL Private	Hydrovac Date	or SL Inspection	Sample Location	Round	Tier 1 Status	SLE Public	SLE Private	SL Replaced Date	Comments
LI13620			10/25/2018				ND		ND		1016 Harmon								kitchen					Filtered and line replaced	
LI12027			10/14/2018				6		ND		218 Behndere								bathroom					Not Residential	
LI15746			11/08/18				1		ND		1813 N. Stevenson								bathroom					Replaced 5/22/18	
LI11002			10/3/2018				ND		ND		2021 N. Vernon								kitchen					Copper to Copper 10/4/18	
LI09610			9/19/2018				ND		ND		2902 Camden								kitchen					Hold time error, no Paperwork	
LI12032			10/15/2018				ND		ND		2420 Levern								kitchen					SL Replaced 9/24/18	
LH98149			8/7/2018				ND		ND		3602 Douglas								kitchen					replaced 6/18/18	
LH95962			7/26/2018				1		ND		3212 Beechwood								kitchen					Galvanized to Galvanized 10/4/18	
LI14841			11/6/2018				ND		ND		414 Mason								kitchen					no confirmation	
LI14839			11/6/2018				ND		ND		729 Prospect								kitchen					no confirmation	
LI14840			11/6/2018				2		ND		617 Lynn Pl.								kitchen					no confirmation	
LI15746			11/19/2018				ND		ND		616 Bejole								kitchen					no confirmation	
LI16509			11/19/2018				ND		ND		415 4th Ave								kitchen					no confirmation	
LI15749			11/7/2018				ND		ND		406 Grand Traverse								kitchen					no confirmation	

SHPO sites, samples obtained, material not verified.